

# HARPAL & ASSOCIATES

ARCHITECTS, ENGINEERS, VALUERS, VASTU CONSULTANTS

APPROVED VALUERS, CONSULTING ENGINEERS

Valuer of : Immovable Property for Bank Sureties

Specialists in : Design, Interior Decoration & Supervisions of Residential Factories  
& Commercial Building's Plans, Details Estimates.

**HARPAL SINGH**

Govt. App. Architect.

Engineers, Regd. Valuers

G.T. Road, Near Sanjay Chowk, Panipat.

(M) 98964-00603

**Ar. Ajay Panghal**

(B.ARCH.)

CA/2023/164575

**(ER. S.K. JAIN CHARTERED ENGINEER)**

B.E. (Civil, A.M.I.E.C.E. (India), F.I.V.

Govt. Regd. Valuer (Govt. of India) Reg. No. CAT-1, 177 OF 1999

Chartered Engineer (India) C.E. 75744/9

Ref. No. H & A/PNP/ CERTIFICATE /2024

Dated: 10-05-2024

## BUILDING STABILITY CERTIFICATE

I HAVE PERSONALLY VISITED & INSPECTED THE SITE EXISTING SCHOOL BUILDING  
SITUATED AT BEHIND OLD BUS STAND, KARNAL (HARYANA)

IN THE NAME OF "P.M. SHRI G.S.S.S." (1938)

Examine The Plan & Specification Of Building Described Below.-

Height of Roof, Actuals Material Used In Its Construction & the Finished Building & Satisfied.

Work Specifications of Building: - Brick Masonry Work in Cement Mortar in Foundation & Super  
Structure, 9" Thick. Bricks Wall, R.C.C. Slab & Stone Tukri Roofing, C.C. & Tile Flooring, Cement  
Plaster Both Side Of Wall, Electricity Fitting Etc.

This Building Structurally Sound & Good Maintained Condition At This Time.

As Per My Observation And Opinion The Building Is Supposed To Be Safe Stable If Periodically  
Repaired And Maintained Where As It Does Not Involve The Unnatural Happening Hence Certified.

Place: - Panipat

Date: - 10-05-2024

  
**ER. SANJEEV KUMAR JAIN**  
B.E. (Civil) A.M.I.E. C.E. (India) A.I.V.  
Chartered Engineers (India) C.E. 75744/9  
G.T. Road, Near Sanjay Chowk, PANIPAT